

**Current Firmware Revision:** 1.01

The following notes provide the revision history and a list of known firmware issues in the current release. For more information please call your Extron Applications Engineer.

**Updated:** July 13, 2009  
**Extron Products Affected:** FOX 2G Tx/Rx AV - MM and SM versions  
**Current Engineering Revision:** E21029

**TECH NOTES**

**Firmware Upload** – The FOX 2G Tx/Rx AV has two firmware files, one for the transmitter and one for the receiver. Each unit should be loaded only with its respective firmware file. Power-cycling and resetting of updated units is required upon completion of a firmware update.

**KNOWN ISSUES**

The following is a list of known firmware issues found in Firmware Version 1.01.

**No known issues**



**Extron USA - West**  
 Headquarters  
 +800.633.9876  
Inside USA / Canada Only  
 +1.714.491.1500  
 +1.714.491.1517 FAX

**Extron USA - East**  
 +800.633.9876  
Inside USA / Canada Only  
 +1.919.863.1794  
 +1.919.863.1797 FAX


**Extron Europe**  
 +900.3987.6673  
Inside Europe Only  
 +31.33.453.4040  
 +31.33.453.4050 FAX

**Extron Middle East**  
 +971.4.2991800  
 +971.4.2991880 FAX

**Extron Asia**  
 +800.7339.8766  
Inside Asia Only  
 +65.6383.4400  
 +65.6383.4664 FAX

**Extron Japan**  
 +81.3.3511.7655  
 +81.3.3511.7656 FAX

**Extron China**  
 +400.883.1568  
Inside China Only  
 +86.21.3760.1568  
 +86.21.3760.1566 FAX




---



---

## FIRMWARE RELEASE HISTORY

**Released Version: 1.01****Affects: Engineering Revision:** prior to E21029**Firmware Revision:** 1.00**Date of Occurrence:** Units shipped prior to July 2009

The following is a list of changes and fixes in this release.

**Improved output voltage levels** – The default input gain for composite video was set too high, causing improper output voltage levels.



Extron USA - West  
Headquarters  
+800.633.9876  
Inside USA / Canada Only  
+1.714.491.1500  
+1.714.491.1517 FAX

Extron USA - East  
+800.633.9876  
Inside USA / Canada Only  
+1.919.863.1794  
+1.919.863.1797 FAX

Extron Europe  
+800.3987.6673  
Inside Europe Only  
+31.33.453.4040  
+31.33.453.4050 FAX

Extron Middle East  
+971.4.2991800  
+971.4.2991880 FAX

Extron Asia  
+800.7339.8766  
Inside Asia Only  
+65.6383.4400  
+65.6383.4664 FAX

Extron Japan  
+81.3.3511.7655  
+81.3.3511.7656 FAX

Extron China  
+400.883.1568  
Inside China Only  
+86.21.3760.1568  
+86.21.3760.1566 FAX